



鉄骨部材リスト

符号	部材	継手部	備考
SG1	H-175-175-7-11	JF3 JP1	
SG2	H-175-90-5-8	JF3 JP2	
SG3	H-150-150-7-10	JF2 JP3	
SG4	H-148-100-6-9	JF2 JP4	
SG5	H-150-75-5-7	JF2 JP5	
SG6	H-125-125-6-9	JF2 JP6	
SG7	H-100-100-6-8	JF1 JP7	
SG8	H-294-200-8-12	JF4	
SG1A	BH-175-175-12-19	JF3	
SC1	φ-216.3×8.2	JB10	
SC2	φ-165.2×5.0	JB7	
SC3	φ-101.6×4.2	JB4	
SC4	φ-89.1×4.2	JB3	
SC5	φ-76.3×3.2	JB2	
SC6	H-125-125-6-9	JB9	φ-50@150をワ工に施工
SC3A	φ-101.6×4.2	JB6	
SC4A	φ-89.1×4.2	JB5	
SB1	H-175-175-7-11	JP1	
SB2	H-175-90-5-8	JP2	
SB3	H-150-150-7-10	JP3	
SB4	H-148-100-6-9	JF2 JP4	
SB5	H-150-75-5-7	JF2 JP5	
SB6	H-125-125-6-9	JP6	
SB7	H-100-100-6-8	JP7	
SB8	H-125-60-6-8	JP8	
SB9	C-75-40-5-7	JP10	
SB10	C-75-75-4.5	JP12 JP13	
SB11	BH-175-175-12-19	JP1	
SB12	H-125-125-6-9	JP6	φ-50@150をワ工に施工
SB13	C-100-50-5-7.5	JP11	
SB14	H-150-150-7-10	JP3	φ-75@150をワ工に施工
SB15	2C-100-50-20-3.5	JP11	板厚C-6 H.1.B 1-M16 @600
SBc1	H-175-175-7-11	-	先端を75mmまで削り落とす。(ハンサ付)
SBc2	H-175-90-5-8	-	"
SBc3	H-150-150-7-10	-	"
SBc4	H-148-100-6-9	-	"
SBc5	H-150-75-5-7	-	"
SBc6	H-125-125-6-9	-	"
SBc7	H-100-100-6-8	-	"
SBc8	H-125-60-6-8	-	"
SBc9	H-125-125-6-9	-	φ-50@150をワ工に施工
SBc1A	BH-175-175-12-19	JF3	先端を75mmまで削り落とす。(ハンサ付)

X5列鉄骨詳細図 1:40